

APPENDIX A

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
	171-07 Baisley Boulevard (Getty)			
PL-10001	P-011273	GPMI Site Remediation files (171-07 Baisley Boulevard)	GPMI-REM-00405	N/A
PL-10002	P-009425	GPMI Site Remediation files (171-07 Baisley Boulevard)	GPMI-REM-00691	N/A
PL-10003	P-008265	GPMI Site Remediation files (171-07 Baisley Boulevard)	GPMI-REM-00774	N/A
PL-10004	P-007980	GPMI Site Remediation files (171-07 Baisley Boulevard)	GPMI-REM-00831	N/A
PL-10005	P-007290	GPMI Site Remediation files (171-07 Baisley Boulevard)	GPMI-REM-00892	N/A
PL-10006	P-006572	GPMI Site Remediation files (171-07 Baisley Boulevard)	GPMI-REM-00979	N/A
PL-10007	P-010699	GPC Site Remediation file (171-07 Baisley Boulevard)	GPC-NYCREM-000428	GPC-NYCREM-000438
	177-90 South Conduit Avenue (ExxonMobil)			
PL-10009	P-025010	Lancaster Laboratories Analytical Report; Sample Number: WW3298568	XOM-NYC-REM-006722	XOM-NYC-REM-006810
PL-10030	P-009468	Fax from Frank DeVita to Gail Helfrick transmitting Quarterly Monitoring Report	XOM-NYC-REM-006876	XOM-NYC-REM-006893
PL-10166	P-013193	Community Air Monitoring Plan	XOM-NYC-REM-007681	XOM-NYC-REM-007686
PL-10305	P-010611	Mobile Service Station 177-90 South Conduit Blvd Queens	XOM-NYC-REM-008675	XOM-NYC-REM-008680
PL-10318	P-011356	Spill Investigation Number 9312565 Mobil S/S 177-90 South Conduit Ave Springfield Gardens New York N.Y. (The Site) - Petroleum Bulk Storage (PBS) Number 2-156957	XOM-NYC-REM-008730	XOM-NYC-REM-008735
PL-10403	P-016047	Site Status Update Report, Mobil Station 17-G90; PS Form 3811; Domestic Return Receipt	XOM-NYC-REM-009491	XOM-NYC-REM-009758
PL-10405	P-014788	Mobil Service Station 17-G90 177-90 South Conduit Ave Springfield Gardens New York	XOM-NYC-REM-009760	XOM-NYC-REM-009762
PL-10453	P-023180	Corrective Action Plan, 177-90 South Conduit	XOM-NYC-REM-010848	XOM-NYC-REM-010946
PL-10455	P-023181	Addendum 1 to 08/29/2002 Revised Corrective Action Plan, 177-90 South Conduit	XOM-NYC-REM-010948	XOM-NYC-REM-010948
PL-10458	P-011868	Off-Site Remediation System Design Report (Interim Remedial Measure)	XOM-NYC-REM-011011	XOM-NYC-REM-011113
PL-10459	P-010843	Remedial Feasibility Summary, 177-90 South Conduit	XOM-NYC-REM-011114	XOM-NYC-REM-011158
PL-10461	P-011938	The Source For Environmental Risk Mgmt Data	XOM-NYC-REM-011164	XOM-NYC-REM-011250
PL-10466	P-012973	Mobil SS# 17-G90 177-90 South Conduit Ave Springfield Gardens New York NYSDEC Spill #8807862 9312565 0110430 And 0205068	XOM-NYC-REM-011259	XOM-NYC-REM-011332
PL-10468	P-011996	Site Investigation And Monitoring Activities Drywell Removal And Remediation Activities	XOM-NYC-REM-011337	XOM-NYC-REM-011356
PL-10475	P-012575	Subsurface Investigation Report	XOM-NYC-REM-011455	XOM-NYC-REM-011619
PL-10479	P-005302	Mobil Station #17-G90 177-90 South Conduit Ave Springfield Gardens New York	XOM-NYC-REM-011880	XOM-NYC-REM-011952
PL-10615	P-012975	Design Report For Permanent Remediation Systems; 177-90 South Conduit	XOM-NYC-REM-013426	XOM-NYC-REM-013532
PL-10616	P-012311	Final Corrective Action Plan; 177-90 South Conduit	XOM-NYC-REM-013533	XOM-NYC-REM-013844
PL-10617	P-024732	Closure Report For The Excavation Of One (1) 1000 Gallon Underground Storage Tank At Mobil Service Station #17-G90	XOM-NYC-REM-013845	XOM-NYC-REM-013881
PL-10640	P-013093	Letter from Anthony Sigona to Melissa Winsor RE Comments on Design Report for Permanent Remediation Systems	XOM-NYC-REM-014049	XOM-NYC-REM-014050
PL-10681	P-012651	177-90 South Conduit Order On Consent	XOM-NYC-REM-014225	XOM-NYC-REM-014245
PL-10685	P-012315	Springfield Gardens New York DEC Order On Consent	XOM-NYC-REM-014274	XOM-NYC-REM-014297

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-10700	P-010570	DEC Letter providing comments on off-site work RE Spill Investigation Number 9312565 Mobil S/S 177-90 South Conduit Ave Springfield Gardens New York N.Y. (The Site) - Petroleum Bulk Storage (PBS) Number 2-156957	XOM-NYC-REM-014376	XOM-NYC-REM-014383
PL-10795	P-013454	Monitoring Well Installation And Groundwater Flow Investigation Report -- 177-90 South Conduit	XOM-NYC-REM-015587	XOM-NYC-REM-015890
PL-10797	P-016035	Fax and letter from GES RE Drywell Activity at 177-90 South Conduit	XOM-NYC-REM-015892	XOM-NYC-REM-015974
PL-10801		Corrective Action Plan For Mobil Service Station Number 17-G90	XOM-NYC-REM-016031	XOM-NYC-REM-016037
PL-10802	P-005824	Stipulation Pursuant To Section 17-0303 Of The Environmental Conservation Law And Section 176 Of The Navigation Law By: Mobil Bus. Res. Corporations	XOM-NYC-REM-016038	XOM-NYC-REM-016046
PL-10822	P-012153	Spill Investigation Number 8807862 9312565 0110430 And 0205068 - Project Identification Number (PIN) 02421 - Mobil S/S 177-90 South Conduit Ave Springfield Gardens New York N.Y. (The Site) - Petroleum Bulk Storage (PBS) Number 2-156957	XOM-NYC-REM-016145	XOM-NYC-REM-016152
PL-10881		Supplemental Site Remediation Files: Temporary Systems Shut Down Request (177-90 South Conduit Ave)	XOM-NYC-SUPP-SRF-0016539	XOM-NYC-SUPP-SRF-0016539
PL-10987	P-005438	NYSDEC Spill Report Form;Spill Number 9604204	XOM-NYC-REM-074265	XOM-NYC-REM-074268
PL-10991	P-004051	NYSDEC Spill Report Form;Spill Number 9313596	XOM-NYC-REM-074278	XOM-NYC-REM-074279
PL-10993	P-002966	NYSDEC Spill Report Form;Spill Number 9206408	XOM-NYC-REM-074281	XOM-NYC-REM-074282
PL-10994	P-001409	NYSDEC Spill Report Form;Spill Number 8804365	XOM-NYC-REM-074283	XOM-NYC-REM-074283
PL-10996	P-006175	Exxon RAS #3-1583 178-02 Union Turnpike/Flushing 550 Gallon Tanks / Disposition	XOM-NYC-REM-074286	XOM-NYC-REM-074287
PL-10997	P-006604	Exxon RAS #3-1583 178-02 Union Turnpike/Flushing DEC# 97-04251	XOM-NYC-REM-074288	XOM-NYC-REM-074290
PL-11020	P-005460	Facility Information Report	XOM-NYC-REM-074526	XOM-NYC-REM-074534
PL-11021	P-011571	Branded Exxon RAS Number 3-1583 178-02 Union Turnpike Flushing New York NYSDEC Case Numbers 94-11551 97-04251	XOM-NYC-REM-074535	XOM-NYC-REM-074564
PL-11024	P-005531	Exxon Service Station RAS #3-1583 178-02 Union Turnpike Flushing New York Flushing New York NYSDEC #9411551	XOM-NYC-REM-074569	XOM-NYC-REM-074571
PL-11062	P-005944	Facility Information Report	XOM-NYC-REM-074949	XOM-NYC-REM-074967
PL-11066	P-002208	Results Of The Sensitive Receptor Survey At Exxon Service Station Number 3-1583	XOM-NYC-REM-074971	XOM-NYC-REM-074991
	188-06 Hillside Ave Sunoco			
PL-11078	P-001827	Letter from Carl Borkland to New York City Fire Department	SUN-MDL-013250	SUN-MDL-013273
PL-11079	P-001673	Analysis Report - EPA 602 - SW-846 8020	SUN-MDL-013274	SUN-MDL-013281
	244 Linden Boulevard			
PL-11080	P-025216	Sunoco Site Remediation Files	SUN-MDL-015708	N/A
PL-11081	P-024510	Project Status Report January 2005 - June 2005;NYSDEC Spill # 96-01355	SUN-MDL-015727	SUN-MDL-015738
PL-11085	P-024830	Project Status Report July 2004 - December 2004;NYSDEC Spill # 99-100659	SUN-MDL-015745	SUN-MDL-015764
PL-11102	P-005882	Subsurface Investigation Results Linden Blvd Elmont New York	SUN-MDL-015853	SUN-MDL-015879
PL-11104	P-005869	Ka-Pa Holding Corp. 244 Linden Blvd Elmont NY	SUN-MDL-015880	SUN-MDL-015881
	82-48 Woodhaven Boulevard			

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-11114	P-006033	Status Update Exxon Facility RAS Number 3-7084 82-48 Woodhaven Blvd Glendale New York NYSDEC Case Number 93-09178	2MDLCP00488634	2MDLCP0488641
PL-11117	P-001984	Tankfield Excavation Assessment	2MDLCP00488921	2MDLCP0488948
PL-11118	P-005836	Soil Sampling And Well Installation Report Exxon Service Station RAS Number 3-7084 82-48 Woodhaven Blvd Glendale New York NYSDEC Case Number 93-09178	2MDLCP00488949	2MDLCP0488979
PL-11120	P-018399	Exhibit E; Underground Storage Tank Information	2MDLCP00488982	2MDLCP0488982
PL-11121	P-008711	Simplicity Monthly Compliance Report For Tosco Mktg Co Inc	2MDLCP00488983	2MDLCP0488985
PL-11122	P-008300	Certificate Of Tightness;Work Order #: 121082	2MDLCP00488986	2MDLCP0488987
PL-11137	P-012950	Branded Exxon RAS Number 3-7084 82-48 Woodhaven Blvd Glendale New York NYSDEC Case Number 93-09178	2MDLCP00489006	2MDLCP0489021
PL-11140	P-013986	Site Status Update Report Branded Exxon RAS Number 3-7084 82-48 Woodhaven Blvd Glendale New York NYSDEC Case Number 93-09178	2MDLCP00489061	2MDLCP0489075
PL-11141	P-004044	Tank - Field Excavation Assessment	2MDLCP00489076	2MDLCP0489171
PL-11144		Site Remediation Documents (84-48 Woodhaven Boulevard)	XOM-NYC-REM-075100	
PL-11145		Site Remediation Documents (84-48 Woodhaven Boulevard)	XOM-NYC-REM-075103	
PL-11153		Site Remediation Documents (84-48 Woodhaven Boulevard)	XOM-NYC-REM-075497	
PL-11154		Site Remediation Documents (84-48 Woodhaven Boulevard)	XOM-NYC-REM-075599	
PL-11157		Site Remediation Documents (84-48 Woodhaven Boulevard)	XOM-NYC-REM-075667	
PL-11162		Site Remediation Documents (84-48 Woodhaven Boulevard)	XOM-NYC-REM-075837	
PL-11184		Site Remediation Documents (84-48 Woodhaven Boulevard)	XOM-NYC-REM-087199	
	138-50 Hillside Avenue			
PL-11233	P-018011	Exxon Site Remediation File 138-50 Hillside Avenue: Letter from NYSDEC to Kleinfelder discussing review of supplemental subsurface investigation	XOM-NYC-SUPP-SRF-0000504	N/A
PL-11234	P-018018	Exxon Site Remediation File 138-50 Hillside Avenue: Letter from Kleinfelder to NYSDEC summarizing reported release	XOM-NYC-SUPP-SRF-0000510	N/A
PL-11235	P-017420	Exxon Site Remediation File 138-50 Hillside Avenue: NYSDEC Letter to Kleinfelder	XOM-NYC-SUPP-SRF-0000519	N/A
PL-11255	P-018088	Exxon Site Remediation File 138-50 Hillside Avenue: Supplemental Subsurface Investigation Report	XOM-NYC-SUPP-SRF-0000608	XOM-NYC-SUPP-SRF-0000694
PL-11257	P-017926	Exxon Site Remediation File 138-50 Hillside Avenue: Station Upgrade Activity Report	XOM-NYC-SUPP-SRF-0000726	XOM-NYC-SUPP-SRF-0000773
PL-11260	P-017725	Exxon Site Remediation File 138-50 Hillside Avenue: Site Status Update Report	XOM-NYC-SUPP-SRF-0000828	N/A
PL-11261	P-017543	Exxon Site Remediation File 138-50 Hillside Avenue: Site Status Update Report	XOM-NYC-SUPP-SRF-0000850	N/A
PL-11273	na	Exxon Site Remediation File 138-50 Hillside Avenue, DEC Spill Report	XOM-NYC-SUPP-SRF-0038156	XOM-NYC-SUPP-SRF-0038159
PL-11301	P-001618	Annual Rent Verification	XOM-NYC-REM-039942	XOM-NYC-REM-039962
PL-11337	P-004182	NYSDEC Spill Report Form;Spill Number 9402398	XOM-NYC-REM-040848	XOM-NYC-REM-040849
PL-11338	P-006698	NYSDEC Spill Report Form;Spill Number 9801762	XOM-NYC-REM-040850	XOM-NYC-REM-040851
PL-11339	P-004458	NYSDEC Spill Report Form;Spill Number 9409159	XOM-NYC-REM-040852	XOM-NYC-REM-040852
PL-11340	P-010736	NYSDEC Spill Report Form;Spill Number 0109472	XOM-NYC-REM-040853	XOM-NYC-REM-040854
PL-11341	P-010023	NYSDEC Spill Report Form;Spill Number 0101410	XOM-NYC-REM-040855	XOM-NYC-REM-040856

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-11346	P-007745	FDNY Violation Order E 22432, 138-50 Hillside Boulevard	XOM-NYC-REM-040865	XOM-NYC-REM-040867
PL-11357	P-023566	Letter from NYSDEC to Mobil evaluating Tank(s) Status	XOM-NYC-REM-040897	XOM-NYC-REM-040898
PL-11361	P-005583	Petroleum Bulk Storage Inspection Report 09/30/96;Inspection Number 2648	XOM-NYC-REM-040905	XOM-NYC-REM-040907
PL-11369	P-004911	Environmental Quick Hit List Corrective Action Plan (CAP) Form 1 Of 2	XOM-NYC-REM-040931	XOM-NYC-REM-040935
PL-11386	P-013601	Certificate Of Underground Storage Tank System Testing	XOM-NYC-REM-041033	XOM-NYC-REM-041041
PL-11388	P-007756	TANKOLOGY Service Request to replace lightbulbs on Veeder Root 250	XOM-NYC-REM-041051	XOM-NYC-REM-041053
PL-11392	P-005919	Invoice 206656; Tankology Tank Testing, 138-50 Hillside Ave.	XOM-NYC-REM-041071	XOM-NYC-REM-041077
PL-11413	P-011398	Email dated 05/22/2003 RE Resolution of Summons Concerning 178-02 Union turnpike (E111-22 Re: G2T GWK HMB)	XOM-NYC-REM-041160	XOM-NYC-REM-041161
PL-11414	P-011310	FDNY Violation Order, 138-50 Hillside Boulevard	XOM-NYC-REM-041162	XOM-NYC-REM-041190
PL-11415	P-011376	Various email correspondence between Exxon and Veeder Root	XOM-NYC-REM-041191	XOM-NYC-REM-041224
PL-11429	P-002151	Notice Of Violation	XOM-NYC-REM-041275	XOM-NYC-REM-041276
144-10 Hillside Blvd				
PL-11439	P-012512	Hess Site Remediation File, 144-10 Hillside Avenue: Spill Closure Report	HESS100688	N/A
PL-11443		Hess Site Remediation File, 144-10 Hillside Avenue:	HESS 113522	N/A
PL-11447	P-025082	Hess Site Remediation File, 144-10 Hillside Avenue: Spill Closure Report	HESS115868	N/A
PL-11461	P-007509	Hess Site Remediation File, 144-10 Hillside Avenue: Site Assesment Report	HESS335931	N/A
PL-11463	P-007163	Hess Site Remediation File, 144-10 Hillside Avenue: UST Closure Report	HESS336131	N/A
PL-11465	P-012926	Hess Site Remediation File, 144-10 Hillside Avenue: Spill Report and No Further Remediation Letter from DEC	HESS336172	N/A
PL-11466	P-012890	Hess Site Remediation File, 144-10 Hillside Avenue: Spill Report and No Further Remediation Letter from DEC	HESS336175	N/A
PL-11475	P-010488	Hess Site Remediation File, 144-10 Hillside Avenue: Triannual Groundwater Status Report	HESS336244	N/A
PL-11477	P-009156	Hess Site Remediation File, 144-10 Hillside Avenue: Site Status Update Report	HESS336260	N/A
PL-11480	P-008211	Hess Site Remediation File, 144-10 Hillside Avenue: Volatile Organic Analysis Data	HESS336288	N/A
PL-11484	P-007212	Hess Site Remediation File, 144-10 Hillside Avenue: Volatile Organic Analysis Data	HESS336298	N/A
PL-11489	P-019113	Hess Site Remediation File, 144-10 Hillside Avenue	HESS336316	N/A
PL-11510	P-020427	138-50 Jamaica Avenue, DEC Spill Report (also XOM-NYC-REM-040848 to 040857)	XOM-NYC-REM-040848	XOM-NYC-REM-040857
84-02 (84-04) Parsons Boulevard				
PL-11673	P-021991	Site Remediation file, 84-04 Parsons Blvd, DEC Correspondence	NYC-MPEXP-E0275456	NYC-MPEXP-E0275457
PL-11689	P-023255	Quarterly Monitoring Information: July through September 2002	XOM-NYC-REM-018749	XOM-NYC-REM-018751
PL-11700	P-023257	Personnel Record of Mark Fuessinger: Inventory Records	XOM-NYC-REM-018778	XOM-NYC-REM-018784
PL-11704	P-010689	NYSDEC Spill Report Form; Spill No. 89-12458	XOM-NYC-REM-018792	XOM-NYC-REM-018794

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-11705	P-003733	NYSDEC Spill Report Form;Spill Number 9306830	XOM-NYC-REM-018795	XOM-NYC-REM-018796
PL-11706	P-001935	NYSDEC Spill Report Form;Spill Number 9007892	XOM-NYC-REM-018797	XOM-NYC-REM-018798
PL-11707	P-001526	NYSDEC Spill Report Form;Spill Number 8900535	XOM-NYC-REM-018799	XOM-NYC-REM-018800
PL-11708	P-001725	NYSDEC Spill Report Form;Spill Number 8912458	XOM-NYC-REM-018801	XOM-NYC-REM-018802
PL-11728	P-025042	Site Investigation: Tyree	XOM-NYC-REM-018912	XOM-NYC-REM-018942
PL-11734	P-024448	Soil Gas Survey: Tyree	XOM-NYC-REM-019089	XOM-NYC-REM-019131
PL-11758	P-024447	Tyree Site Assessment With Sensitive Receptor Data	XOM-NYC-REM-019938	XOM-NYC-REM-019992
PL-11760	P-024879	Site status update report; includes Domestic Mailing Receipt	XOM-NYC-REM-020001	XOM-NYC-REM-020041
PL-11762	P-013781	Quarterly Monitoring Report April Through June 2003	XOM-NYC-REM-020082	XOM-NYC-REM-020119
PL-11865	P-004724	Mobil Service Station Number 17-GD9 84-04 Parsons Blvd Jamaica New York NYSDEC Spill Number 89-12458	XOM-NYC-REM-020890	XOM-NYC-REM-020901
PL-11930	NA	84-04 Parsons Blvd, Exxon Supplemental Site Remediation Files: Letter from NYSDEC to Kleinfelder Approving Soil Vapor Extraction/Air Sparge feasibility Study Work Plan	XOM-NYC-SUPP-SRF-0027223	XOM-NYC-SUPP-SRF-0027234
PL-11934	NA	84-04 Parsons Blvd, Exxon Supplemental Site Remediation Files: Letter from Mobil Oil Company to Marley Pumu Company RE 80-04 Parsons Leak	XOM-NYC-SUPP-SRF-0027293	XOM-NYC-SUPP-SRF-0027294
PL-11936	NA	84-04 Parsons Blvd, Exxon Supplemental Site Remediation Files: Letter from Mobil Oil Corporation to Marley Pump Company RE 84-04 Parsons Leak	XOM-NYC-SUPP-SRF-0027308	XOM-NYC-SUPP-SRF-0027308
PL-11939	NA	84-04 Parsons Blvd, Exxon Supplemental Site Remediation Files: Letter from Groundwater Technology to Mobil RE Site Status	XOM-NYC-SUPP-SRF-0027349	XOM-NYC-SUPP-SRF-0027350
PL-11962	NA	84-04 Parsons Blvd, Exxon Supplemental Site Remediation Files: Geological services Corporation Letter to NYSDEC	XOM-NYC-SUPP-SRF-0027482	XOM-NYC-SUPP-SRF-0027486
PL-12007	NA	84-04 Parsons Blvd, Exxon Supplemental Site Remediation Files: Site Status Update Report	XOM-NYC-SUPP-SRF-0028677	XOM-NYC-SUPP-SRF-0028715
PL-12018	NA	84-04 Parsons Blvd, Exxon Supplemental Site Remediation Files: Revised investigation Work Plan with Domestic Registered Mail Return Receipt	XOM-NYC-SUPP-SRF-0029344	XOM-NYC-SUPP-SRF-0029352
PL-12019	NA	84-04 Parsons Blvd, Exxon Supplemental Site Remediation Files: Remedial Feasibility Summary	XOM-NYC-SUPP-SRF-0029353	XOM-NYC-SUPP-SRF-0029359
165-25 Liberty Avenue				
PL-12068	P-017677	Quarterly Monitoring Report First Quarter 2007;NYSDEC Spill Number 99-13468	BPCITYNY0000001	BPCITYNY0000016
PL-12070	P-017845	Ground Water Monitoring Report - Third Quarter 2007 NYSDEC Spill Number 99-13468 Former Amoco BP Service Station Number 11009 165-25 Liberty Ave St. Albans Queens County New York	BPCITYNY0000082	BPCITYNY0000121
PL-12075	P-009818	Remedial Action Plan: 165-25 Liberty Ave., Spill No. 99-13468	BPCNY0038402	BPCNY0038491
PL-12079	P-018603	Subsurface Hydrocarbon Assessment Report for Amoco Station No. 11009; NYSDEC Spill No. 99-13468 (245 pages) March 23, 2000; BPCNY0038617	BPCNY0038617	BPCNY0038861
PL-12085	P-018730	correspondence to FDNY from BP re: BP Service Station 11009; WRA Monthly Statistical Inventory Reconciliation Reports, multiple dates 2002-2004	BPII000364920	BPII000364987

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-12089	NA	165-25 Liberty Avenue BP Site Remediation Files: Natural Work Team Meeting, Delta Environmental	BPCNY0038993	BPCNY0039005
PL-12097	NA	165-25 Liberty Avenue BP Site Remediation Files: April 2004 Monthly Remediation Operation and Maintenance Report	BPCNY0039135	BPCNY0039149
PL-12100	NA	165-25 Liberty Avenue BP Site Remediation Files: Quarterly Monitoring Report, 1Q 2003	BPCNY0039227	BPCNY0039242
	165-01 Hillside Avenue			
PL-12194	P-018060	Exxon site Remediation Files: Letter from DEC to Ken Drake, Exxon	XOM-NYC-SUPP-SRF-0001125	XOM-NYC-SUPP-SRF-0001126
PL-12195	P-018017	Exxon site Remediation Files: Letter from DEC to Ken Drake, Exxon	XOM-NYC-SUPP-SRF-0001127	XOM-NYC-SUPP-SRF-0001128
PL-12196	P-017883	Exxon site Remediation Files: DEC Letter to Kleinfelder	XOM-NYC-SUPP-SRF-0001129	XOM-NYC-SUPP-SRF-0001130
PL-12197	P-017808	Exxon site Remediation Files: Kleinfelder FOIL Correspondence with DEP	XOM-NYC-SUPP-SRF-0001133	XOM-NYC-SUPP-SRF-0001138
PL-12198	P-018151	Exxon site Remediation Files:	XOM-NYC-SUPP-SRF-0001162	XOM-NYC-SUPP-SRF-0001187
PL-12199	P-018145	Exxon site Remediation Files: Supplemental subsurface Investigation Plan	XOM-NYC-SUPP-SRF-0001188	XOM-NYC-SUPP-SRF-0001197
PL-12200	P-018054	Exxon site Remediation Files: Kleinfelder Letter to NYSDEC	XOM-NYC-SUPP-SRF-0001198	XOM-NYC-SUPP-SRF-0001224
	162-35 North Conduit Avenue			
PL-12239	P-009596	PBS #2-482498 NYSDEC #90-07853 Mobil Service Station #17-JH5 162-35 North Conduit Ave Springfield Gardens New York	XOM-NYC-REM-044401	XOM-NYC-REM-044420
PL-12240	P-009597	PBS #2-482498 NYSDEC #90-07853 Mobil Service Station #17-JH5 162-35 North Conduit Ave Springfield Gardens New York	XOM-NYC-REM-044421	XOM-NYC-REM-044456
PL-12252	P-015888	Mobil Services Station Number 17-JH5 162-35 North Conduit Ave Springfield Gardens New York NYSDEC Case Number 90-07853 PBS Number 2-482498	XOM-NYC-REM-043704	XOM-NYC-REM-043705
PL-12253	P-015747	Domestic Return Receipt and Remedial Action Plan	XOM-NYC-REM-043851	XOM-NYC-REM-043904
PL-12260		Executive Summary from Hydrogeological Assessment	XOM-NYC-REM-043165	XOM-NYC-REM-043167
PL-12278	P-023580	Site Status Report with Domestic Return Receipt	XOM-NYC-REM-043234	XOM-NYC-REM-043277
PL-12281	P-010008	Project Initiation Form with Monthly Monitoring Report	XOM-NYC-REM-043287	XOM-NYC-REM-043292
PL-12295	P-003080	Carbon Installation Cost Estimate Mobil Station # 17-JH5 162-35 North Conduit Ave Springfield Gardens New York	XOM-NYC-REM-043369	XOM-NYC-REM-043380
PL-12300	P-023589	Relevant Site History	XOM-NYC-REM-043398	XOM-NYC-REM-043399
PL-12372	P-015438	ExxonMobil Service Station 10/1/03 Site Visits/Project Reviews	XOM-NYC-REM-043708	XOM-NYC-REM-043714
PL-12374	P-014473	Mobil Service Station #17-JH5 162-35 North Conduit Ave Springfield Gardens New York NYSDEC Spill #90-07853	XOM-NYC-REM-043720	XOM-NYC-REM-043723
PL-12377	P-008874	Mobil Station #17-JH5 162-35 North Conduit Ave Springfield Gardens NYSDEC Spill #90-07853	XOM-NYC-REM-043727	XOM-NYC-REM-043728
PL-12390	P-015747	Hydrogeological Assessment	XOM-NYC-REM-043905	XOM-NYC-REM-043947
PL-12397	P-016022	Remedial Action Plan with Domestic Return Receipt	XOM-NYC-REM-044106	XOM-NYC-REM-044148
PL-12398	P-016302	Quarterly Monitoring Reports 2002	XOM-NYC-REM-044149	XOM-NYC-REM-044149
PL-12405	P-010868	Mobil Service Station #17-JH5 162-35 North Conduit Ave Springfield Gardens New York PBS #2-482498	XOM-NYC-REM-044236	XOM-NYC-REM-044250

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-12462	P-023637	July - September 1993 Status Report Period Covering: July 1 - September 30 1993	XOM-NYC-REM-047455	XOM-NYC-REM-047458
PL-12479	P-003027	August 1992 Status Report Mobil Station # 17-JH5 162-35 North Conduit Ave Springfield Gardens New York	XOM-NYC-REM-047558	XOM-NYC-REM-047560
PL-12504	P-009521	Non-Hazardous Waste Manifest Document Number NHZ 09130	XOM-NYC-REM-047804	XOM-NYC-REM-047806
PL-12506	P-004396	Uniform Hazardous Waste Manifest;State Manifest Document Number NJA 1301696	XOM-NYC-REM-047810	XOM-NYC-REM-047821
PL-12507	P-005993	Uniform Hazardous Waste Manifest;State Manifest Document Number 91336	XOM-NYC-REM-047822	XOM-NYC-REM-047823
PL-12738	NA	Exxon Supplemental Site Remediation Files: Leak/Pollution incident Report	XOM-NYC-SUPP-SRF-0040049	XOM-NYC-SUPP-SRF-0040050
	162-16 Union Turnpike			
PL-12869	P-012876	Correspondence between shell/Consultants/DEC re: Spill # 9613464, 9808828 2000-2003	BQSJMS02708	BQSJMS02719
PL-12879	P-007790	Shell Site Remediation files- environmental site assesment	BQSJMS03278	BQSJMS03309
PL-12883	N/A	Shell Site Remediation File- Well Installation Report	BW-IS-GES000800	BW-IS-GES000829
PL-12884	N/A	Shell Site Remediation File- Corrective Action Plan Extension Request	BW-IS-GES000860	BW-IS-GES000898
	108-01 Atlantic Avenue			
PL-12927		Envirotrac letter to M. Mulqueen w/ Environmental Site Assessment attached	BQ-CN-DK-00001	BQ-CN-DK-00022
PL-12929		Shell Incident Notification to NYSDEC	BQ-CN-DK-00075	BQ-CN-DK-00080
PL-12931		Site Remediation materials -- 108-01 Atlantic Avenue	BQSJMS07435	BQSJMS07435
PL-12933		Site Status Report	BQSJMS07438	BQSJMS07450
PL-12940		Site Plans -- 108-01 Atlantic Avenue	BQSJMS07468	BQSJMS07472
PL-12947		Soil Disposal information	BQSJMS07531	BQSJMS07532
PL-12948		Field Work Request	BQSJMS07533	BQSJMS07534
PL-12949		Field Work Request	BQSJMS07535	BQSJMS07536
PL-12958		Letter to Kerry Foley, NYSDEC, attaching GRASP information	BQSJMS07611	BQSJMS07628
PL-12962	P-016438	550-Gallon Heating Oil Underground Storage Tank (UST) Closure NYSDEC Spill #: 04-11343 Shell Service Station # 138695 108-1 Atlantic Ave Richmond Hill NY	N/A	N/A
PL-12963	P-001711	Tank closure report, 108-01 Atlantic Avenue	BQ-CN-DK00216	BQ-CN-DK00240
PL-12964	P-018742	Site remediation materials, 108-01 Atlantic Avenue	BQ-IS-GES000023	BQ-IS-GES000023
PL-12965	P-018743	Site remediation materials, 108-01 Atlantic Avenue	BQ-IS-GES000024	BQ-IS-GES000042
PL-12969	P-009095	Site remediation materials 108-01 Atlantic Avenue	BQSJMS07644	BQSJMS07682
PL-12971	P-005902	UST Removal Report, 108-01 Atlantic Avenue	BQSJMS07709	BQSJMS07757
	104-09 Atlantic Avenue			
PL-12973		Tank testing results w/ J. Howard transmittal letter	HESS 94467	HESS 94510
PL-12979		R. Ehrlich to E. Harden intra-Hess memo with response	HESS 94640	HESS 94641
PL-12980		S. Tyree letter to NYC Fire Dep't with attachments	HESS 94643	HESS 94654
PL-12983		Monitoring well abandonment report	HESS 94664	HESS 94667
PL-12987		Environmental inspection reports	HESS 94681	HESS 94694
PL-12988		Tank testing results	HESS 94695	HESS 94714
PL-12992		Tank testing results w/ S. Germann transmittal letter	HESS 94740	HESS 94745
PL-12995		Tank testing results w/ S. Germann transmittal letter	HESS 94788	HESS 94830
PL-12997		Tank testing results w/ J. Howard transmittal letter	HESS 94847	HESS 94855

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-13062	P-010992	D.Lee (Hess) letter to S. Sangesland (NYSDEC) attaching Station Upgrade Report, 104-09 Atlantic Avenue	HESS094409	HESS094443
PL-13064	P-013031	Notice of Site Closure w/ DEC correspondence	HESS094511	HESS094513
PL-13067	P-002143	M. Mengel (Hess) letter to K. Tang (NYSDEC) with attachments	HESS094558	HESS094565
PL-13068	P-002058	M. Mengel (Hess) letter to E. Sullivan (NYSDEC) with attachments	HESS094566	HESS094574
PL-13069	P-005337	D. Johnson (Hess) letter to C. Tomasello (NYSDEC) with attached Environmental Assessment Report	HESS094575	HESS094622
PL-13073	P-004941	Site Remediation File, 104-09 Atlantic Avenue	HESS113522	HESS113551
	105-15 Merrick Boulevard			
PL-13075	P-017922	Letter from T. Festa to G. Singh re: Spill Number 96-05038 Citgo Service Station 105-15 Merrick Blvd Jamaica New York Remedial Investigation Report And Supplemental Ground-Water Investigation Report	NYC-MOREAU-N-00003031	N/A
PL-13080	P-020611	Letter from T. Festa (NYSDEC) to G. Singh re: 105-15 Merrick Blvd	NYC-LBG-E0034657	NYC-LBG-E0034658
PL-13081	P-020612	Letter from T. Festa (NYSDEC) to G. Singh re: 105-15 Merrick Blvd	NYC-LBG-E0034659	NYC-LBG-E0034660
PL-13086	P-020617	Letter from M. Moulik (MIG Environmental) to T. Festa (NYSDEC) with Groundwater Investigation Report, 105-15 Merrick Boulevard	NYC-LBG-E0034730	NYC-LBG-E0034813
PL-13087	P-020618	Limited Subsurface Investigation for 105-15 Merrick Blvd., prepared by EMI	NYC-LBG-E0034814	NYC-LBG-E0034865
PL-13088	P-020619	Site Investigation Report for 105-15 Merrick Boulevard, prepared by MIG	NYC-LBG-E0034866	NYC-LBG-E0034938
PL-13089	P-020620	Letter from V. Pucciarrello to T. Festa (NYSDEC) re 105-15 Merrick Blvd with Remedial Investigation Report	NYC-LBG-E0034939	NYC-LBG-E0034991
	108-46 Merrick Boulevard			
PL-13149	P-020582	Letter from T. Festa (NYSDEC) to Meir Adry (Orna), 108-46 Merrick Blvd.	NYC-LBG-E0034450	NYC-LBG-E0034450
PL-13158	P-020591	Letter from J. DeMartinis (JR Holzmacher) to T. Festa (NYSDEC) w/attachments, re 108-46 Merrick Blvd.	NYC-LBG-E0034514	NYC-LBG-E0034540
PL-13176	P-021952	Site Remediation File, 108-46 Merrick Blvd dated 11/22/2006	NYC-MPEXP-E0275202	NYC-MPEXP-E0275204
PL-13187	P-021963	Site Remediation File, 108-46 Merrick Blvd.	NYC-MPEXP-E0275255	NYC-MPEXP-E0275255
PL-13192	P-021968	Site Remediation File, 108-46 Merrick Blvd dated 5/10/2005	NYC-MPEXP-E0275274	NYC-MPEXP-E0275274
PL-13203	P-021979	Site Remediation File, 108-46 Merrick Blvd dated 3/1/2006	NYC-MPEXP-E0275367	NYC-MPEXP-E0275378
PL-13207	P-021983	Site Remediation File, 108-46 Merrick Blvd dated 5/16/2008	NYC-MPEXP-E0275423	NYC-MPEXP-E0275438
	113-21 Merrick Boulevard			
PL-13208		Letter from M. Haggerty (NYSDEC) to R. Caputo (Kleinfelder)	XOM-NYC-SUPP-SRF-0019992	XOM-NYC-SUPP-SRF-0020002
PL-13219		Service Request/Service Completed Notice from IPT to GSC	XOM-NYC-SUPP-SRF-0020047	XOM-NYC-SUPP-SRF-0020048
PL-13219A		FOIL Response letter from John Dyland of NYCDEP	XOM-NYC-SUPP-SRF-0020049	XOM-NYC-SUPP-SRF-0020050
PL-13271		Site Status Update from Kleinfelder to M. Haggerty (NYSDEC)	XOM-NYC-SUPP-SRF-0020574	XOM-NYC-SUPP-SRF-0020604

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-13363	P-013801	ExxonMobil Service Station 113-21 Merrick Blvd Jamaica NY - Spill Investigation Number 9814185 - Petroleum Bulk Storage (PBS) Facility Number 2-156922	XOM-NYC-REM-028855	XOM-NYC-REM-028857
PL-13365	P-005380	Mobil Service Station SS# 17-GVE 113-21 Merrick Rd St. Albans New York NYSDEC Spill #: 96-01682	XOM-NYC-REM-028861	XOM-NYC-REM-028863
PL-13369	P-010353	POR - Complete	XOM-NYC-REM-028876	XOM-NYC-REM-028879
PL-13382	P-013870	GES Field Log; Boring: MW-1	XOM-NYC-REM-028946	XOM-NYC-REM-028949
PL-13389	P-005346	NYSDEC Spill Report Form;Spill Number 9601682	XOM-NYC-REM-028993	XOM-NYC-REM-028994
PL-13390	P-023430	NYSDEC Spill Report Form;Spill Number 0012866	XOM-NYC-REM-029004	XOM-NYC-REM-029004
PL-13391	P-001612	NYSDEC Spill Report Form;Spill Number 8906399	XOM-NYC-REM-029005	XOM-NYC-REM-029011
PL-13391A	P-001612	NYSDEC Spill Report Form;Spill Number 0012866 as printed on 06/25/2001	XOM-NYC-REM-029009	XOM-NYC-REM-029010
PL-13391B	P-001612	FAX RE: "Incoming Shipments"	XOM-NYC-REM-029011	XOM-NYC-REM-029011
PL-13392	P-009747	Daily Log 3/9/01	XOM-NYC-REM-029012	XOM-NYC-REM-029016
PL-13442	P-015132	GSC Site Summary And Work Scope	XOM-NYC-REM-029572	XOM-NYC-REM-029574
PL-13443	P-011077	Mobil Service Station #17-GVE 113-21 Merrick Blvd Jamaica New York NYSDEC # 0012866	XOM-NYC-REM-029575	XOM-NYC-REM-029576
PL-13444	P-010483	UNTITLED Site Remediation Narrative as produced by XOM	XOM-NYC-REM-029577	XOM-NYC-REM-029584
PL-13446	P-014555	Mobil Service Station #17-GVE 113-21 Merrick Blvd Jamaica New York NYSDEC Spill #00-12866	XOM-NYC-REM-029678	XOM-NYC-REM-029711
PL-13447	P-010279	Mobil Service Station #17-GVE 113-21 Merrick Blvd Jamaica New York NYSDEC # 0012866	XOM-NYC-REM-029712	XOM-NYC-REM-029802
PL-13449	P-016065	Site Status Update Report to J. Rommel with Domestic Return Receipt	XOM-NYC-REM-029806	XOM-NYC-REM-029828
<u>166-60 Sutphin Blvd (Citgo)</u>				
PL-13457	P-017351	Getty Site Remediation Files 116-60 Sutphin Blvd: Quarterly Monitoring Report	GPC-NYCREM-000442	GPC-NYCREM-000459
PL-13466	P-011598	Getty Site Remediation Files 116-60 Sutphin Blvd: Quarterly Monitoring Report w/ cover letter from Delta to Scott Hanley	GPC-NYCREM-000614	GPC-NYCREM-000623
PL-13467	P-012286	Getty Site Remediation Files 116-60 Sutphin Blvd: w/ cover letter from Delta to Scott Hanley	GPC-NYCREM-000624	GPC-NYCREM-000632
PL-13471	P-015585	116-60 Sutphin Blvd: Getty Site Remediation Files	GPMI-NYC-000982	N/A
<u>137-10 94th Ave. (BP-Amoco)</u>				
PL-13489	P-017929	Ground Water Monitoring Report - First Quarter 2008 NYSDEC Spill Number 97-09661 Former Amoco BP Service Station Number 00560 137-10 94th Ave Jamaica Queens County New York	BPCITYNY0002480	BPCITYNY0002513
PL-13533	P-007345	Fax from K. Kleaka to Eric Lismann; Letter from Impact Environmental Consulting RE Phase I for 137-10 94th Avenue	BPCNY0004913	BPCNY0004916
PL-13536	P-006632	Fax from Gene Schmidt to Andra Puris	BPCNY0004921	BPCNY0004931
PL-13537	P-006211	Email from AMOCO to Baltec RE 137-10 94th Ave. Jamaica NY	BPCNY0004932	BPCNY0004932
PL-13538	P-007822	Spill Number 97-09661 Amoco S/S 560 137-10 94th Ave Jamaica New York, Quarterly Activity Report	BPCNY0004933	BPCNY0004951
PL-13543	P-009172	Email chain regarding SS# 560 Abandonment	BPCNY0004959	BPCNY0004962
PL-13544	P-008125	NYSDEC Letter to BP Amoco RE 137-10 94th Avenue, Jamaica. NY	BPCNY0004963	BPCNY0004965

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-13546	P-008347	Monitoring Well Installation At Amoco S/S Located At 137-10 94th Ave Queens Spill #: 9709661 And 9909107	BPCNY0004966	BPCNY0004967
PL-13550	P-008181	Spill Number 97-09661 Amoco S/S 560 137-10 94th Ave Jamaica New York; Summary of Sensitive Receptor Survey	BPCNY0004975	BPCNY0004979
PL-13694	P-007419	Waste Material Profile	BPCNY0005562	BPCNY0005564
PL-13698	P-009239	Incoming Load Ticket # 13327; 137-10 94th Avenue	BPCNY0005572	BPCNY0005575
PL-13724	P-006967	Spill Number 97-09661 Amoco S/S 560 137 - 10 94th Ave Jamaica New York	BPCNY0005868	BPCNY0006014
PL-13754	P-016043	Report Tracking Sheet;Service Station #560 Quarterly Monitoring Report, 3Q 2004	BPCNY0006933	BPCNY0006948
PL-13757	P-006885	John F. Kennedy Airport Light Rail System Project Amoco Service Station 137-10 94th Ave Jamaica NY 11435 Block 9990 Lot 5	BPCNY0006956	BPCNY0007084
PL-13758	P-009357	Underground Storage Tank Excavation Assessment Report November 10 2000	BPCNY0007085	BPCNY0007094
PL-13761	P-010080	Letter from Delta to NYSDEC RE 137-10 94th Avenue, Jamaica NY	BPCNY0007106	BPCNY0007107
PL-13763	P-009300	Letter from Michael Gomez to Aaron Lapine	BPCNY0007108	BPCNY0007115
PL-13772	P-007036	Environmental Site Assessment Phase I Investigation: 137-10 94th Avenue, September 25 1998	BPCNY0007249	BPCNY0007326
	<u>148-12 Rockaway Blvd (Sunoco)</u>			
PL-14185		Hess Site File: Letter from Merit Oil to DEC	HESS33048	HESS33049
PL-14225	P-017455	Hess Site Remediation File: No Further Action Letter	HESS890078	HESS890081
PL-14227	P-017870	Hess Site Remediation File: Update Report and Site Closure Request for 148-27 Liberty Avenue	HESS890084	HESS890117
PL-14244	P-017355	Hess Site Remediation File: Tri-Annual Monitoring Report with GW Data from November 1996-2007	HESS890289	HESS890324
PL-14249		Hess Site File: Letter from Amerada Hess to DEC	HESS627532	HESS627533
PL-14251		Hess Site File: NYSDEC - Region 2 Site Summary	HESS628347	HESS628381
PL-14261		Hess Site File: NYSDEC - Region 2 Site Summary	HESS799701	HESS799734
PL-14280	P-016197	Second Tri-Annual 2004 Update Report Hess Station 32521 - Liberty 148-27 Liberty Ave Jamaica New York NYSDEC Spill #96-06415	HESS97269	HESS97305
	<u>154-10 Rockaway Blvd.</u>			
PL-14281	P-017285	Shell Site Remediation Files	BQ-IS-GES000063	N/A
PL-14282	P-016918	Shell Site Remediation Files	BQ-IS-GES000084	N/A
PL-14283	P-017021	Shell Site Remediation Files	BQ-IS-GES000102	N/A
PL-14284	P-017165	Shell Site Remediation Files	BQ-IS-GES000120	N/A
PL-14285	P-025193	Shell Site Remediation Files	BQ-IS-GES000141	N/A
PL-14286	P-020458	Shell Site Remediation Files	NYC-LBG-03324	N/A
PL-14287	P-020459	Shell Site Remediation Files	NYC-LBG-03341	N/A
PL-14288	P-007017	Shell Site Remediation Files	BQ/CO/PS000413	BQ/CO/PS000434
	<u>156-07 Rockaway Blvd (Getty 343)</u>			
PL-14306	P-012601	Getty Properties site remediation files: 156-07 Rockaway Blvd.; DEC Letter to Getty with attached materials	GPMI-REM-03869	N/A
PL-14307	P-010464	Getty Properties site remediation files: Email(s) from Ewald to Asehirli with attached materials	GPMI-REM-04174	N/A

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-14308	P-009009	Getty Properties site remediation files: FAX re Getty Geoprobe Proposal	GPMI-REM-04304	N/A
PL-14310	P-006610	Getty Properties site remediation files: Tyree Tank Upgrade/Status Report	GPMI-REM-04595	GPMI-REM-04691
PL-14311	P-012389	Getty Properties site remediation files: Email(s) from Lindell to Ewald and other materials	GPMI-REM-05739	N/A
	161-51 Baisley Blvd			
PL-14313	P-016332	Getty Properties Site Remediation files: 2004 Site file	GPMI-REM-01080	N/A
PL-14314	P-014894	Getty Properties Site Remediation files: 2003 Site File	GPMI-REM-01253	N/A
PL-14315	P-011187	Getty Properties Site Remediation files: 2002 Site File	GPMI-REM-01407	N/A
PL-14316	P-010103	Getty Properties Site Remediation files: 2001 Site File	GPMI-REM-01534	N/A
PL-14317	P-008612	Getty Properties Site Remediation files: 2000 Site File	GPMI-REM-01656	N/A
PL-14318	P-007470	Getty Properties Site Remediation files: 1999 Site File	GPMI-REM-01744	N/A
PL-14319	P-007022	Getty Properties Site Remediation files: 1998 Site File	GPMI-REM-01954	N/A
PL-14319A		GPMI Field Notes for 161-51 Baisley Boulevard	GPMI-REM-02027	GPMI-REM-02028
PL-14689		165-25 Liberty Avenue, Site Work Order History	BPCNY0040555	BPCNY0040570
PL-14690		Site Remediation and Tank Closure Report, 117-07 Guy Brewer Blvd.	CNY-FOIL-GB-00013	CNY-FOIL-GB-00057
PL-14691		Spill Report Form and PBS Certificate for 117-07 Guy Brewer Blvd.	CNY-FOIL-GB-00224	CNY-FOIL-GB-00232
PL-14692		DEC letter attaching stipulation and corrective action plan for 117-07 Guy Brewer Blvd.	CNY-FOIL-GB-00001	CNY-FOIL-GB-00004
PL-14693		DEC letter attaching stipulation and corrective action plan for 117-07 Guy Brewer Blvd.	CNY-FOIL-GB-00005	CNY-FOIL-GB-00008
PL-14694		Letter from DEC regarding Monitoring Well Installation at 117-07 Guy Brewer Blvd.	CNY-FOIL-GB-00009	CNY-FOIL-GB-00009
PL-14695		Letter from DEC regarding Monitoring Well Installation at 117-07 Guy Brewer Blvd.	CNY-FOIL-GB-00010	CNY-FOIL-GB-00010
PL-14696		Letter from DEC requesting submission of RAP for 117-07 Guy Brewer Blvd.	CNY-FOIL-GB-00011	CNY-FOIL-GB-00011
PL-14697		Letter from DEC approving RAP for 117-07 Guy Brewer Blvd	CNY-FOIL-GB-00012	CNY-FOIL-GB-00012
PL-14698		Site Plan and Analytical Results for 117-07 Guy Brewer Blvd	CNY-FOIL-GB-00058	CNY-FOIL-GB-00068
PL-14699		Site Plan and Analytical Results for 117-07 Guy Brewer Blvd	CNY-FOIL-GB-00069	CNY-FOIL-GB-00091
PL-14700		Site Plan and Analytical Results for 117-07 Guy Brewer Blvd	CNY-FOIL-GB-00092	CNY-FOIL-GB-00114
PL-14701		Site Plan and Analytical Results for 117-07 Guy Brewer Blvd	CNY-FOIL-GB-00114	CNY-FOIL-GB-00135
PL-14702		Site Investigation and Remediation Update for 117-07 Guy Brewer Blvd	CNY-FOIL-GB-00136	CNY-FOIL-GB-00223
PL-14703		Site Investigation and Remediation Update for 117-07 Guy Brewer Blvd	CNY-FOIL-GB-00233	CNY-FOIL-GB-00251
PL-14704		Site Investigation and Remediation Update for 117-07 Guy Brewer Blvd	CNY-FOIL-GB-00252	CNY-FOIL-GB-00271
PL-14705		Record of Converstaion at 84-04 Parsons Boulevard	XOM-NYC-REM-019133	XOM-NYC-REM-019141
PL-14706		Amerada Hess: Site Summary for 148-27 Liberty Avenue	HESS97847	HESS97883
PL-14707		DEC Databse Extract(s): 84-04 Parsons Boulevard -- Spill Nos. 8900535, 8912458 & 9007892	N/A	N/A
PL-14708		NYSDEC Bulk Storage Database Search Details: 84-04 Parsons Blvd.		

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-14709		DEC Database Extract(s): 177-90 South Conduit Avenue -- Spill Nos. 8807862, 9312565, 9414767, 0205068, 0205081, 0210154, 0210416, 0507321 & 0507321		
PL-14710		NYSDEC Bulk Storage Database Search Details: 177-90 South Conduit Avenue		
PL-14711		DEC Database Extract(s): 148-27 Liberty Avenue -- Spill No. 9606415		
PL-14712		NYSDEC Bulk Storage Database Search Details: 148-27 Liberty Avenue		
PL-14713		DEC Database Extract(s): 117-07 Guy R. Brewer Boulevard -- Spill Nos.		
PL-14714		NYSDEC Bulk Storage Database Search Details: 117-07 Guy R. Brewer Boulevard		
PL-14715		DEC Database Extract(s): 113-21 Merrick Boulevard -- Spill Nos. 9814185, 0012866, 8906399 & 9601682		
PL-14716		NYSDEC Bulk Storage Database Search Details: 113-21 Merrick Boulevard		
PL-14717		DEC Database Extract(s): 138-50 Hillside Avenue -- Spill Nos. 0101410, 9402398, 9409159 & 9801762		
PL-14718		NYSDEC Bulk Storage Database Search Details: 138-50 Hillside Avenue		
PL-14719	138-50 Hillside Avenue		XOM-NYC-SUPP-SRF-0000630	
PL-14720	Letter from DEC to Hess w/ Attached Stipulation	HESS 97707	HESS 97715	
PL-14721	DEC - Region 2 Site Summary	HESS 97847	HESS 97848	
PL-14722	Letter from DEC to Hess s/ executed stipulation	HESS 97699	HESS 97703	
PL-14723	Internal Memorandum Summarizing History of this Site	HESS 97740	HESS 97746	
PL-14724	Letter from Hess to DEC re: Tri-Annual 2003 Update Report	HESS 97778	HESS 97817	
PL-14725	Invoice from Summit Drilling Company	HESS 97752	HESS 97756	
PL-14726	Letter from Hess to DEC re: Tri-Annual 2004 Update Report	HESS 97269	HESS 97305	
PL-14727	UST Closure Report	BQ-IS-GES000607	BQ-IS-GES000627	
PL-14728	Site Status Update Report	BQ-IS-GES000899	BQ-IS-GES000946	
PL-14729	UST and Hydraulic Lift Closure w/ cover letter	BQ-IS-GES000632	BQ-IS-GES000799	
PL-14730	Rob Rule email	BQSJMS02683	BQSJMS02683	
PL-14731	Subsurface Investigation Report with cover letter	XOM-NYC-REM-046189	XOM-NYC-REM-046260	
PL-14732	Site Status Update and Closure Request	XOM-NYC-SUPP-SRF-0039103	XOM-NYC-SUPP-SRF-0039112	
PL-14733	Sensitive Receptor Survey with mailing receipt	XOM-NYC-SUPP-SRF-0039152	XOM-NYC-SUPP-SRF-0039178	
PL-14734	Letter from W. Gorman to FDNY	XOM-NYC-SUPP-M&C-000060	XOM-NYC-SUPP-M&C-000064	
PL-14735	Station Upgrade Activity Report	XOM-NYC-SUPP-SRF-0001316	XOM-NYC-SUPP-SRF-0001401	
PL-14736	Kleinfelder waste monitoring program	XOM-NYC-SUPP-SRF-0001412	XOM-NYC-SUPP-SRF-0001416	
PL-14737	Waste Shipment Documentation Form	XOM-NYC-SUPP-SRF-0001417	XOM-NYC-SUPP-SRF-0001423	

APPENDIX A

PLAINTIFF'S TRIAL EXHIBIT NO.		Description	Beginning Bates No.	End Bates No.
PL-14738		165-25 Liberty Avenue, Hazardous Waste Manifest	BPCNY0040398	BPCNY0040398
PL-14739		165-25 Liberty Avenue, Site Work Order History	BPCNY0040555	BPCNY0040570
PL-14740		Spill Response Report	SUN-MDL-013292	SUN-MDL-013293
PL-14741		FDNY NOV for 188-06 Hillside	SUN-MDL-013284	
PL-14742		Correspondence from Sun to NYSDEC and FDNY re Spill 890301	SUN-MDL-013282	SUN-MDL-013283
PL-14743		Letter from Sun re. pollution claims at 188-06 Hillside	SUN-MDL-013287	SUN-MDL-013289
PL-14744		multiple docs, inclusing PBS application for 188-06 Hillside Avenue	SUN-MDL-022957	SUN-MDL-022974
PL-14745		DEP application for registration for gasoline dispensing site	SUN-MDL-022931	SUN-MDL-022934
PL-14746		NYSDEC multi site Spill report forms, including 188-06 Hillside	NYC-LBG-E0050442	NYC-LBG-E0050456
PL-14747		UST closure report for 188-06 Hillside Avenue	NYC-MP-EXP-E0002904	NYC-MP-EXP-E0002996
PL-14748		DEC letter to Sunoco attaching remediation stipulation agreement	NYC-MP-EXP-E0002884	NYC-MP-EXP-E0002888
PL-14749		analytical data for 188-06 Hillside Avenue	NYC-MP-EXP-E00056767	NYC-MP-EXP-E00056772
PL-14750		Remedial Action Plan w/ Cover Letter	NYC-MP-EXP-E0003030	NYC-MP-EXP-E0003067
PL-14751		244 Linden Site Remediation Files	SUN-MDL-022827	SUN-MDL-022847
PL-14752		Branded Marketing Retail Facilities System Update; November 2000 emails concerning inventory variances	SUN-MDL-022587	SUN-MDL-022588
PL-14753		Environmental Incident Report informing NYSDEC of gasoline spill associated with a tank overfill	SUN-MDL-022710	SUN-MDL-022727
PL-14754		Tank Testing Reports	SUN-MDL-015939	SUN-MDL-015941
PL-14755		UST Upgrade Project Status Report, multisites	NYC2_0109122	NYC2_0109187
PL-14756		Preliminary Corrective Action Plan, 167-02 Baisley Blvd	NYC2_0110061	NYC2_0110087
PL-14757		Bi-Monthly Status Report, DEC UST Order of Consent, multisite, including 167-02 Baisley Blvd.	NYC2_0069368	NYC2_0069530
PL-14758		Stipulation of Agreement for the 113th Precinct Remedial Action	NYC2_0121166	NYC2_0121177
PL-14759		UST Updgrade Project Status Report, multisites, including 113th Precinct	NYC2_0114243	NYC2_0114277
PL-14760		Activities Summary Report, UST Closures, 113th Precinct	NYC-0057287	NYC-0057304
PL-14761		Affidavit of Tank Removal, 113th Precinct	NYC-0059232	NYC-0059232
PL-14762		Evaluation of Remediation System Removal, Results and Recommendation after Data Collection, 113th Precinct	NYC-0043058	NYC-0043179
PL-14763		Evlauation of Remediation System Performance	NYC-0043040	NYC-0043057
PL-14764		NYCDDC UST Program System Performance data for 113th precinct period through June 2001	NYC-0043420	NYC-0043462
PL-14765		Site Specific Investigation and Remedial Plan Report- Phase 1 (168-02 91st Avenue)	NYC2_0109308	NYC2_0109601
PL-14766		Design Analysis Report (168-02 91st Avenue)	NYC2_0109644	NYC2_0109765
PL-14767		Site Specific Investigation and Remedial Plan Report- Phase 2 (168-02 91st Avenue)	NYC2_0109188	NYC2_0109307
PL-14768		DEC Letter approving SSIR	NYC2_0109770	NYC2_0109770
		DEC Spill Report Form- 95-11826	NYC_MP_EXP_003682	NYC_MP_EXP_003683